



1989 Toyota Camry "Door not Opened" Repair



Removed inner door panel



Disengaged door hinge caused "Door not opened"



Engaged by wire resulted "Door opened"

Yellow plastic clip deteriorates by heat and causes being disengaged door opening mechanism. Then, it results in deactivation of door opening.

Simple wired connection fix works.

Automobile mechanical design seems based on Low-Tech.