




1993 Mercury Sable Wagon Constant Control Relay Module Replacement



Old Relay Module Installed




Connector & Bracket



New & Old Constant Control Relay Module

While vehicle is running, engine stall tends to happen.

According to OBDI scanner, the cause was occasional contact failure of fuel pump relay installed in the constant control relay module (one of relays installed).



Replaced