



1993 Mercury Sable Wagon Power Steering Pump Replacement




Power Steering Pump & Pulley


Power steering oil started leaking from cracked plastic reservoir of power steering pump.




Old Power Steering Pump Installed



Pulley Remover Tool



Removing Pulley





Pulley Removed



Crack on Plastic Return Hose Inlet (Design Flaw)




Pressure Hose Disconnected



Power Steering Pump Removed (with Bracket)



Power Steering Pump Removed (No Bracket)



New Power Steering Pump Installed (No Pulley)




Pulley Munter Tool



Mounting Pulley



Pulley Mounted



Replaced