


1995 Toyota Camry Battery Terminal Replacement



Negative battery terminal (right) replaced (Faulty insufficient contact without filing off black paint)



Good looking problematic battery terminal sold in market (Before filing off red paint on surface)



Filed to get sufficient electrical contact removing unnecessary red paint which is not conductive



Ready to use (Negative black terminal also filed as it should be)