

2007 Pontiac Vibe Oxygen Sensor Replacement



Heat Shield Cut Out

OBDII scanner exhibited diagnostic error on oxygen sensor.

There was difficulty of disengaging and pulling oxygen sensor through a small hole, a portion of the heat shield (top; looks like a key hole) was cut out by angle grinder to ease handling of tool and oxygen sensor.



Oxygen Sensor Connector Disconnected (System Side)



Oxygen Sensor Connected to Exhaust Pipe



New & Old Oxygen Sensor



Old Oxygen Sensor from Denso