

1993 Mercury Sable Wagon Speedometer Replacement



Old Speedometer (Center of Instrument Cluster) Installed

The needle of speedometer started jumping vigorously.


Both the cable and speedometer (one of meters in instrument cluster) were replaced.



Removing




Instrument Cluster Removed



Old Speedometer (Instrument Cluster)




New Speedometer (Instrument Cluster)



Cable Receptacle on New Instrument Cluster



New Cable (Left to speedometer, Right to cable linkup)



Instrument Cluster Side

Cable Passed through the Hole (Old is Gray, New is Black)



Cable Appeared in Instrument Cluster Side



Old Cable



Replaced