


1995 Toyota Camry Power Steering Pump & Hose Replacement

(A) Power Steering Pump




Before



Return Hose & Pressure Feed Union Bolt Removed



Power steering oil leaked from the pump.




Old & New Power Steering Pump



Old Power Steering Pump Fully Being Drenched by Power Steering Oil




New Power Steering Pump



Return Hose, Bracket, New Power Steering Pump Assembled with Parts



Old Power Steering Pump Removed



Replaced (Clean; No Oil Leak)

(B) Power Steering Pump Pressure Feed Tube



Before (Leaking oil)




Old Power Steering Pump Pressure Feed Tube with Crack

The crack caused power steering oil leak.



Old Power Steering Pump Pressure Feed Tube Removed



Power Steering Pump Pressure Feed Tube Replaced