

1999 Toyota Avalon Hood Support Replacement



New (Top) & Old (Bottom) Hood Support



Old (Right; Passenger Side) & (Left; Driver's Side)



New (Right) & (Left)

Old hood support became not stuck out the heavy engine room hood due to leaking gas stored inside. Even though one side of hood supports gets problem, it is better to replace both side of hood supports. Old and new hood supports have different type of lower metal fittings.