



Repair Bidet Water Leak


Old Version (Astor)



Before (Hose Cracked)



After (Replaced by Hose for Drip Irrigation)



Water Leaked Due to Seriously Cracked Hose (Low Quality Hose Used)

New Version (Brondell)



Splash Nozzle



Splash Nozzle Cleaner & Guard



Water off



Water on to Nozzle Cleaner

Splash water direction and strength are simply controlled by rotating the knob.



New ("Brondell": Metal Tube & Connectors) & Old Version ("Astor": Plastic Tube & Connectors)



Ugly Old-fashioned Control Box & Thick Body Due to Wiring Hose Inside



Smart Looking Control Box & Thin Body (Water Pass through Inside Plastic Mold)

"Brondell" is much better than "Astor" and the sales price is competitive.