


Repair DVD Recorder

Toshiba DVD recorder (RD-XS32SU) installs a HDD (Hard Disk Drive) and a DVD-RAM/R/RW drive as multimedia recording equipment.

HDD was able to record multimedia programs but DVD-RAM/R/RW drive lost both playing and recording function. The DVD-RAM/R/RW drive installed on Toshiba DVD recorder was a regular DVD drive with ATA (AT Attachment) parallel interface that was installed in IBM PCs.



DVD-RW Drive with ATA Parallel Interface Piggy-backed, Analog TV Connected by Composite Video and Audio



DVD Drive Piggy-backed (ATA Power & Data Connected)

Removed Old DVD Drive




Broken DVD-RAM Drive (Toshiba Samsung)

New DVD-RW Drive Replaced (Sony)



Bolt Hole Position of Side Bracket had to be Shifted Backward a bit



Replaced & Working