


## **Woodwork Rack**








#1 - VLF
#2 - VLB
#3 - VRF
#4 - VRB

	#5 - HF1		#5 - HR1		
	//O LIEO		//O LIDO		
#6 - HF2			#6 - HR2		
	#7 - HF3		#7 - HR3		
#8 - HB1			#8 - HL1		
	//o LIDO		//O		
	#9 - HB2		#9 - HL2		
	#10 - HB3		#10 - HL3		
#11 - Tray x 2					
#12 - Tray x 2					
#13 - Tray x 2					
#44 Tools 0	#44 T 0	#44 T 0	#44 T		
#14 - Tray x 2					

Type-1 Rack Schematic


Misc - Tray x 2

Misc - Tray x 2



#1 - VLF						
#2 - VLB						
#3 - VRF						
#4 - VRB						
	#5 - HR1					
	#6 - HR2					
	#7 - HR3					
	#8 - HR4					
	#9 - HL1					
	#10 - HL2					
	#11 - HL3					
#12 - HB4			#12 - HL4			
#13 - Tray x 2						
#14 - Tray x 2						
#15 - Tray x 2						
#16 - Tray x 2						
#17 - Tray x 2						
#18 - Tray x 2						

Type-2 Rack Schematic







Bottom View of Type 2 Rack



Cut Out from Table Saw



Screw Position View from Outside

Top View of Type 2 Rack




Screw Position View from Inside



Type 2 Rack Loaded



Type 3 Rack not yet Loaded



Plural Type-3 Racks Loaded