

2007 Pontiac Vibe Side Mirror Replacement



Broken Side Mirror (Passenger Side)

When backing up, the side mirror (passenger side) struck garage side wall and the side mirror broke apart.





Door Board Detached

Side Mirror Parts Detached





Attachment Base Exposed (Inside & Outside)



Replaced (Inside & Outside)