

Big Dent on Left Rear Bumber



Dent Repair Trial by Pulling the Dent (Failed)

Pasting plastic clips by glue on the dent, pull the clips to outside strongly. The trial did not work.



Rear Bumper Removed

Recent vehicle equips bumper made by reinforced plastic which softens when heat is applied.

After removing rear bumper, pouring hot water to the dent from rear side of rear bumper, push the dent by foot and hand strongly as soon as possible. The portion of the dent looks recovered as before.





Before

After Dent Repair