

# 1993 Mercury Sable Wagon Windshield Water Hose Repair



Broken Plastic Coupling



Broken Plastic Coupling



Alternative Parts



Repaired