

2007 Pontiac Vibe Drive Belt Replacement




Cracked Drive Belt

Old drive belt exhibited a lot of cracks due to deterioration. The situation was under fracture, nearly break down.



Tension Arm Bolt

By handling tension arm bolt, the drive belt wound firmly can be released or attached.



New Drive Belt Wound